

OCZ SSD Storage Solutions: Firmware Version 2.15

Issues resolved since version 2.13

- Fixed a rare condition that may cause Windows Blue Screen error when the primary-configured drive woke up from either a SATA slumber mode or S3/S4 modes
- Fixed a rare condition that may cause Windows Blue Screen error when the drive was configured as primary with OS installed
- Fixed a corner-case issue that may cause the drive to stutter or Windows freezing screen when a media read error occurred
- Further improved robustness of secure erase operation to prevent possible low-level data structure corruption
- Significantly improved TRIM handling to enhance system stability

Supported Products:

- Deneva 2 C Series
- Talos 2 C Series

enterprise

Known open issue(s):

- Formatting a RAID1 volume takes longer than expected with PMC-Sierra BR-8 HBA